

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

SHENANDOAH-DIVES MILL
(Mayflower Mill)
135 County Road 2
Silverton
San Juan County
Colorado

HAER CO-91

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Jet Lowe, photographer, August 2005

- | | |
|---------|---|
| CO-91-1 | AERIAL VIEW, LOOKING EAST-NORTHEAST, SHOWING THE POWERHOUSE IN THE CENTER, ANIMAS RIVER ON THE RIGHT, AND THE SHENANDOAH-DIVES (MAYFLOWER) MILL AND TAILINGS PONDS IN THE DISTANCE. |
| CO-91-2 | AERIAL VIEW, LOOKING NORTHEAST, SHOWING ANIMAS RIVER IN CENTER FOREGROUND, POWERHOUSE IN LEFT CENTER, AND SHENANDOAH-DIVES (MAYFLOWER) MILL AND TAILINGS PONDS IN DISTANCE. |
| CO-91-3 | AERIAL VIEW OF SHENANDOAH-DIVES (MAYFLOWER) MILL, LOOKING NORTH, WITH FIRST TAILINGS POND TO ITS LEFT. |
| CO-91-4 | AERIAL VIEW OF SHENANDOAH-DIVES (MAYFLOWER) MILL, LOOKING NORTHEAST, WITH TAILINGS POND TO ITS LEFT. |
| CO-91-5 | AERIAL VIEW OF SHENANDOAH-DIVES (MAYFLOWER) MILL, LOOKING WEST, WITH TAILINGS POND IN UPPER LEFT. |

SHENANDOAH-DIVES MILL

HAER CO-91

INDEX TO PHOTOGRAPHS

Page 2

| | |
|----------|--|
| CO-91-6 | AERIAL VIEW OF SHENANDOAH-DIVES (MAYFLOWER) MILL, LOOKING SOUTHWEST, WITH TAILINGS POND IN UPPER RIGHT. |
| CO-91-7 | AERIAL VIEW OF SHENANDOAH-DIVES (MAYFLOWER) MILL LOOKING EAST-NORTHEAST, WITH TAILINGS POND IN FOREGROUND. |
| CO-91-8 | AERIAL VIEW OF SHENANDOAH-DIVES (MAYFLOWER) MILL, LOOKING NORTHEAST, WITH TAILINGS POND IN LEFT FOREGROUND. |
| CO-91-9 | AERIAL VIEW OF SHENANDOAH-DIVES (MAYFLOWER) MILL EAST ELEVATION. |
| CO-91-10 | VIEW, LOOKING NORTH-NORTHWEST, DOWN ARRASTRA GORGE FROM HAZLETON MOUNTAIN TO SHENANDOAH-DIVES (MAYFLOWER) MILL IN DISTANCE. |
| CO-91-11 | VIEW, LOOKING NORTH-NORTHWEST, DOWN ARRASTRA GORGE FROM VICINITY OF SHENANDOAH-DIVES (MAYFLOWER) MINE. |
| CO-91-12 | AERIAL VIEW OF AVALANCHE SPLITLEGS NEAR TOP OF ARRASTRA GORGE. |
| CO-91-13 | AERIAL VIEW, LOOKING WEST-NORTHWEST, OF SILVER LAKE (ELEV. 12,186'). NOTE RUINS OF ROYAL TIGER MINE IN FOREGROUND. |
| CO-91-14 | AERIAL VIEW, LOOKING NORTH, OF SILVER LAKE MINING DISTRICT. |
| CO-91-15 | AERIAL VIEW, LOOKING NORTHEAST, OF SILVER LAKE MINING DISTRICT. |
| CO-91-16 | AERIAL VIEW, LOOKING NORTH, OF SILVER LAKE. NOTE IOWA MINE RUINS AT LEFT CENTER AND SILVER LAKE MINE RUINS BEYOND NORTHWEST SHORE. |
| CO-91-17 | AERIAL VIEW, LOOKING NORTHWEST, OF SILVER LAKE. SHENANDOAH-DIVES (MAYFLOWER) MILL CAN BE SEEN IN THE ANIMAS VALLEY AT TOP CENTER. |

SHENANDOAH-DIVES MILL
HAER CO-91
INDEX TO PHOTOGRAPHS
Page 3

| | |
|----------|--|
| CO-91-18 | AERIAL VIEW, LOOKING NORTHWEST, DOWN ARRASTRA GULCH WITH SHENANDOAH-DIVES (MAYFLOWER) MILL IN THE ANIMAS VALLEY. |
| CO-91-19 | AERIAL VIEW, LOOKING SOUTHWEST, OF SILVER LAKE WEST SHORE WITH RUINS OF SILVER LAKE MINE AT BOTTOM CENTER. NOTE CONTINUITY OF GEOLOGICAL FORMATIONS WHERE BOTTOM OF LAKE CAN BE SEEN. |
| CO-91-20 | AERIAL VIEW OF NORTH STAR MINE PORTAL, LOCATED ON NORTH SLOPE OF LITTLE GIANT PEAK. |
| CO-91-21 | AERIAL VIEW, LOOKING NORTHWEST, OF LITTLE GIANT BASIN. NOTE TREE LINE BEYOND LAKE. |
| CO-91-22 | AERIAL VIEW, LOOKING EAST NORTHEAST, WITH HOWARDSVILLE IN THE CENTER AND ANIMAS FORK ROAD CONTINUING UP THE ANIMAS VALLEY. |
| CO-91-23 | AERIAL VIEW, LOOKING SOUTHWEST, OF LITTLE GIANT BASIN. NOTE TREE LINE AND ABANDONED TRAMWAY TOWER |
| CO-91-24 | AERIAL VIEW, LOOKING EAST, OF NORTH STAR MINE RUINS IN LITTLE GIANT BASIN. |
| CO-91-25 | RUINS OF ADIT (HORIZONTAL MINE ENTRANCE) AND HEADHOUSE AT BASE OF LITTLE GIANT PEAK. VIEW FROM ACROSS VALLEY. |
| CO-91-26 | RUINS OF ADIT (HORIZONTAL MINE ENTRANCE) AND HEADHOUSE AT BASE OF LITTLE GIANT PEAK. VIEW FROM ABOVE. |
| CO-91-27 | RUINS OF ADIT (HORIZONTAL MINE ENTRANCE) AND HEADHOUSE AT BASE OF LITTLE GIANT PEAK. VIEW FROM ABOVE. |
| CO-91-28 | NORTH STAR MINE PORTAL, LOCATED ON NORTH SLOPE OF LITTLE GIANT PEAK. |
| CO-91-29 | AERIAL VIEW OF NORTH STAR MINE PORTAL, LOCATED ON NORTH SLOPE OF LITTLE GIANT PEAK. |

SHENANDOAH-DIVES MILL
HAER CO-91
INDEX TO PHOTOGRAPHS
Page 4

- CO-91-30 AERIAL VIEW, LOOKING NORTH NORTHWEST, OF
ARRASTRA BASIN, SILVER LAKE, AND THE
SHENANDOAH-DIVES (MAYFLOWER) MILL IN DISTANT
ANIMAS VALLEY.
- CO-91-31 AERIAL VIEW, LOOKING WEST NORTHWEST, WITH
REMNANTS OF SURFACE PLANT AT HEAD OF DIVES
BASIN, SOUTHEAST OF LITTLE GIANT PEAK.
- CO-91-32 AERIAL VIEW, LOOKING SOUTHEAST, OF SILVER LAKE,
WITH SILVER LAKE MINE AND MILL RUINS ON NEAR
SHORE.
- CO-91-33 AERIAL VIEW, LOOKING SOUTH, OF ARRASTRA BASIN
AND SILVER LAKE.
- CO-91-34 AERIAL VIEW, LOOKING NORTHWEST, OF ARRASTRA
BASIN AND THE SHENANDOAH-DIVES (MAYFLOWER)
MILL IN DISTANT ANIMAS VALLEY.
- CO-91-35 AERIAL VIEW, LOOKING NORTH NORTHWEST, OF
ARRASTRA GULCH, WITH SILVER LAKE IN
FOREGROUND. NOTE SILVER LAKE MINE AND MILL
RUINS ON FAR SHORE.
- CO-91-36 ZIG-ZAG PACK TRAIL LEADING UP TO SHENANDOAH
DIVES MINE PORTAL, NOTE AVALANCH SPLITLEGS TO
PROTECT TRAM TOWERS.
- CO-91-37 AERIAL VIEW, LOOKING SOUTH, OF SHENANDOAH-
DIVES (MAYFLOWER) MINE PORTAL, IN SHADOW AT
WIDENED END OF ROAD, THREE-EIGHTHS FROM THE
BOTTOM.
- CO-91-38 AERIAL VIEW LOOKING SOUTH SOUTHEAST, OF
SHENANDOAH-DIVES (MAYFLOWER) MINE UPPER TRAM
STATION IN FOREGROUND AND PORTAL ABOVE (IN
SHADOW). NOTE PACK TRAIL BETWEEN MINE HEAD
AND NORTHERN END OF SILVER LAKE, JUST VISIBLE AT
UPPER RIGHT.

SHENANDOAH-DIVES MILL
HAER CO-91
INDEX TO PHOTOGRAPHS
Page 5

| | |
|----------|---|
| CO-91-39 | AERIAL VIEW, LOOKING NORTHWEST, DOWN ARRASTRA GULCH, WITH SHENANDOAH-DIVES MINEHEAD AT CENTER. |
| CO-91-40 | VIEW, LOOKING NORTH NORTHWEST, FROM SHENANDOAH-DIVES (MAYFLOWER) MINEHEAD AREA DOWN ARRASTRA GULCH, WITH MILL IN DISTANT VALLEY. NOTE AVALANCH SPLITLEG AND TRAM TOWER IN LOWER FOREGROUND. |
| CO-91-41 | OVERTURNED CART NEAR SHENANDOAH-DIVES (MAYFLOWER) MINE PORTAL. |
| CO-91-42 | AVALANCHE SPLITLEG AND STEEL TRAM TOWER, ARRASTRA GULCH |
| CO-91-43 | SHENANDOAH-DIVES (MAYFLOWER) MINE PORTAL SITE, LOOKING WEST. NOTE FOUNDATION AT RIGHT AND RADIATOR AT LOWER LEFT, BOTH REMNANTS OF THE DORMITORY. |
| CO-91-44 | SHENANDOAH-DIVES (MAYFLOWER) MINE PORTAL SITE, LOOKING NORTH. NOTE RADIATOR AT LOWER RIGHT. |
| CO-91-45 | DETAIL OF RADIATOR IN CO-91-43 AND CO-91-44. |
| CO-91-46 | RUINS OF SILVER LAKE MINE AND MILL, LOOKING SOUTHEAST. SILVER LAKE IS IN BACKGROUND. |
| CO-91-47 | SOUTH ELEVATION, TRANSFORMER HOUSE, SILVER LAKE MINE AND MILL AT SILVER LAKE. |
| CO-91-48 | REMNANTS OF SILVER LAKE STAMP MILLS, LOOKING WEST. |
| CO-91-49 | REMNANTS OF SILVER LAKE STAMP MILLS, LOOKING NORTH. |
| CO-91-50 | TOWN OF SILVERTON, COLORADO, LOOKING NORTH NORTHEAST. NOTE ANIMAS RIVER IN IDAHO GULCH AT LOWER RIGHT. |

SHENANDOAH-DIVES MILL
HAER CO-91
INDEX TO PHOTOGRAPHS
Page 6

- CO-91-51 TELEPHOTO VIEW (600MM LENS) OF SILVERTON, COLORADO, LOOKING NORTH NORTHEAST. NOTE DURANGO & SILVERTON NARROW GAUGE RAILROAD AT BOTTOM CENTER.
- CO-91-52 GENERAL VIEW, LOOKING EAST NORTHEAST FROM TAILINGS POND DAM, OF SHENANDOAH-DIVES (MAYFLOWER) MILL (115MM LENS).
- CO-91-53 GENERAL VIEW, LOOKING EAST NORTHEAST FROM TAILINGS POND DAM, OF SHENANDOAH-DIVES (MAYFLOWER) MILL (165MM LENS).
- CO-91-54 SHENANDOAH-DIVES (MAYFLOWER) MILL, LOOKING NORTHWEST FROM OFFICE BUILDING. TALLEST BUILDING CONTAINS FINE ORE BIN, WITH THE BALL MILL ROOM TO ITS LEFT. SEE CO-91-56 FOR CONTINUATION TO THE LEFT.
- CO-91-55 VIEW, LOOKING NORTH, OF ENCLOSED CONVEYOR TO CARRY FINE ORE UP TO BIN IN THE TALLEST BUILDING. THE MULTI-WINDOWED PORTION OF BUILDING WITH "MILL TOUR" SIGN HOUSES THE MAINTENANCE SHOP.
- CO-91-56 SHENANDOAH-DIVES (MAYFLOWER) MILL, LOOKING WEST FROM OFFICE BUILDING. NOTE ELECTRICAL SUBSTATION WITH CYLINDRICAL COAL BIN AND TRESTLE BEHIND IT. LIGHT-COLORED BUILDING BEHIND TRESTLE IS FLOTATION CELL ROOM. SEE CO-91-54 FOR CONTINUATION TO THE RIGHT.
- CO-91-57 UNLOADING TRESTLE AND COAL BIN FOR BOILERS AT LOWER END OF MILL. FLOTATION CELL ROOM IS AT RIGHT, WITH THICKENER ROOM BEYOND.
- CO-91-58 NORTHEAST ELEVATION OF FINE ORE BIN PORTION OF MILL BUILDING. NOTE VERTICAL WOOD SIDING.
- CO-91-59 WATER STORAGE TANK ON NORTH SIDE OF MILL, WITH ROD MILL BUILDING IN BACKGROUND.

SHENANDOAH-DIVES MILL

HAER CO-91
INDEX TO PHOTOGRAPHS
Page 7

- CO-91-60 GENERAL VIEW OF MILL, LOOKING WEST NORTHWEST, WITH TRAM HOUSE AND OFFICE BUILDING IN CENTER. COAL BIN AND BOILER HOUSE ARE AT FAR LEFT.
- CO-91-61 VIEW, LOOKING EAST, OF TRAM HOUSE (LEFT) AND OFFICE BUILDING (RIGHT). NOTE TRAM CABLE TENSIONING TOWER ABOVE TRAM HOUSE.
- CO-91-62 WEST ELEVATION OF OFFICE BUILDING
- CO-91-63 VIEW LOOKING SOUTH SOUTHEAST FROM TRAM HOUSE UP ARRASTRA GULCH. NOTE CLEARED PATH THROUGH TREES FOR TRAM.
- CO-91-64 ORE BUCKET ON TRAM. NOTE THAT BUCKET ROLLS ALONG UPPER, STATIONARY SUSPENSION CABLE, PULLED BY LOWER, MOVING TRACTION CABLE. FOREGROUND CABLES ARE FOR BUCKET'S TRIP FROM MINE TO MILL.
- CO-91-65 ENTERING SIDE OF TRAM HOUSE, LOOKING SOUTH SOUTHEAST UP ARRASTRA GULCH. ENTERING ORE BUCKETS ROLLED OF SUSPENSION CABLE ONTO UPPER STEEL RAIL, WHERE THEY WERE DISCONNECTED FROM TRACTION (LOWER) CABLE.
- CO-91-66 TRAM HOUSE INTERIOR, LOOKING WEST. NOTE ARRIVING BUCKET ON RAIL IN CENTER, DEPARTING BUCKET IN LEFT BACKGROUND, TRACTION CABLE IN PULLEYS, AND SUSPENSION CABLE ANGLING DOWN THROUGH FLOOR.
- CO-91-67 TRAM HOUSE INTERIOR, LOOKING SOUTH. NOTE HORIZONTAL, IDLER, BULL WHEEL TO REVERSE DIRECTION OF TRACTION CABLE. TRAM CABLE DRIVE MOTOR (NO LONGER EXTANT) WAS AT MINE END OF TRAM.
- CO-91-68 TRAM HOUSE INTERIOR, LOOKING SOUTHEAST. NOTE TRACTION CABLE BULL WHEEL AND DEPARTING BUCKET "12," STILL ON RAIL AND JUST PRIOR TO ENGAGING TRACTION CABLE.

SHENANDOAH-DIVES MILL
HAER CO-91
INDEX TO PHOTOGRAPHS
Page 8

- | | |
|----------|---|
| CO-91-69 | TRAM HOUSE INTERIOR, LOOKING SOUTHEAST. NOTE DEPARTING ORE BUCKET "12" AND SUSPENSION CABLE ANGLING DOWN THROUGH FLOOR AT LOWER LEFT. LARGE LEVER ON SIDE OF BUCKET ALLOWS IT TO BE ROTATED FOR DUMPING ORE. |
| CO-91-70 | DETAIL OF TRACTION CABLE ENGAGEMENT DEVICE. SMALL, KNOBBED LEVER ON BUCKET HANGER WAS PULLED DOWN BY A CAMEL (FIXED CAM RAIL AT CENTER) AS BUCKET ROLLED PAST IT, CAUSING A CLAMP TO CLOSE AGAINST TRACTION CABLE. A SIMILAR CAMEL (NO LONGER EXTANT) DISENGAGED CLAMP ON RECEIVING SIDE. |
| CO-91-71 | TRAM SUSPENSION CABLE OILING CAR. |
| CO-91-72 | DETAIL VIEW OF TRAM SUSPENSION CABLE OILING CAR. NOTE CIRCULAR TRACTION CABLE CLAMP IN CENTER AND OIL FEED TO CABLE BETWEEN TWO RIGHT-HAND WHEELS. OIL REDUCED FRICTION AND RUST. |
| CO-91-73 | SYMONS SHORT HEAD GYRATORY CONE CRUSHER AND FEED CONVEYOR IN CRUSHING ROOM. |
| CO-91-74 | SYMONS STANDARD HEAD GYRATORY CONE CRUSHER AND FEED CONVEYOR IN CRUSHING ROOM. |
| CO-91-75 | DETAIL OF SYMONS SHORHEAD GYRATORY CONE CRUSHER. |
| CO-91-76 | CRUSHING ROOM AND CONVEYER SYSTEM LOOKING EAST. |
| CO-91-77 | LOOKING WEST ALONG PASSAGE BETWEEN CRUSHING ROOM AND FINE ORE BIN AREA. NOTE STEEL CUSTOM ORE CHUTES IN BACKGROUND. THE FARTHEST BINS WERE LAST USED FOR STORAGE OF BALL MILL BALLS. |
| CO-91-78 | LOOKING EAST ALONG PASSAGE BETWEEN CRUSHING ROOM AND FINE ORE BIN AREA. NOTE BALL MILL BALLS AND CHUTES IN FOREGROUND. |

SHENANDOAH-DIVES MILL
HAER CO-91
INDEX TO PHOTOGRAPHS
Page 9

- | | |
|----------|--|
| CO-91-79 | ROD MILL ROOM, LOOKING EAST, SHOWING DENVER SPIRAL CLASSIFIER, WITH DOMINION ROD MILL IN LEFT BACKGROUND. WATER WAS ADDED TO ORE IN ROD MILL TO MAKE A SLURRY CALLED SLIME. |
| CO-91-80 | DOMINION 8 FT. X 12 FT. ROD MILL, WITH DRIVE MOTOR IN FOREGROUND. |
| CO-91-81 | DETAIL OF MILL FRAMING AT JUNCTION OF FINE ORE BIN AND GRINDING ROOMS, WITH CYLINDRICAL FINE ORE BIN IN BACKGROUND. |
| CO-91-82 | INTERIOR VIEW, LOOKING WEST, OF GRINDING ROOM, WITH MARCY NO. 86 BALL MILL AT CENTER. |
| CO-91-83 | INTERIOR VIEW, LOOKING SOUTHWEST, OF GRINDING ROOM, WITH MARCY NO. 86 BALL MILL IN CENTER. |
| CO-91-84 | GRINDING ROOM, LOOKING EAST. NOTE OVERHEAD BRIDGE CRANE RIDING ON STEEL RAILS SUPPORTED BY WOODEN BEAMS AND CYCLONE CLASSIFIER IN CENTER. AT RIGHT IS TOP PORTION OF FLASH FLOTATION CELL. |
| CO-91-85 | DETAIL OF CYCLONE CLASSIFIER, WITH MARCY NO. 86 BALL MILL BELOW AND BEHIND IT. STRAIGHT HORIZONTAL PIPE IS SLIME FEED FROM ROD MILL. PIPE OUT TOP OF CYCLONE AND CURVING AT LOWER RIGHT CARRIED FINELY GROUND SLIME TO FLOTATION CONDITIONER TANK. PIPE NOT VISIBLE OUT BOTTOM OF CYCLONE CONVEYED COARSER SLIME TO BALL MILL. |
| CO-91-86 | DETAIL OF MARCY NO. 86 BALL MILL. OVAL OPENING, NORMALLY COVERED, ALLOWED REPLACEMENT OF GRINDING BALLS. |
| CO-91-87 | VIEW LOOKING DOWN ON GOLD JIGS, WITH MARCY NO. 86 BALL MILL IN BACKGROUND. |
| CO-91-88 | GOLD JIGS. VERTICAL PLATES AT TOP CENTER FRAME RECTANGULAR INLET OPENINGS VISIBLE IN CO-91-87. |

SHENANDOAH-DIVES MILL
HAER CO-91
INDEX TO PHOTOGRAPHS
Page 10

- CO-91-89 GENERAL ELECTRIC 250-HP SYNCHRONOUS MOTOR FOR MARCY NO. 86 BALL MILL. A PORTION OF BALL MILL IS VISIBLE AT UPPER RIGHT.
- CO-91-90 GENERAL ELECTRIC SYNCHRONOUS MOTOR, SLIP RING END. NOTE THAT OUTSIDE FRAME IS ROTATING ARMATURE, AND STATOR IS IN CENTER. ARCH SUPPORTS BRAKE BAND.
- CO-91-91 LOOKING DOWN ON GENERAL ELECTRIC 250-HP SYNCHRONOUS MOTOR. LARGE HANDWHEEL IN FOREGROUND USED TO TIGHTEN BRAKE BAND AROUND ARMATURE TO STOP BALL MILL AND MOTOR ROTATION.
- CO-91-92 DETAIL OF GENERAL ELECTRIC 250-HP SYNCHRONOUS MOTOR FROM SLIP RING END. NOTE BOLTS AND SPRINGS OF BRAKE BAND, HEAVY-WIRE ARMATURE WINDINGS, AND TIGHTLY WOUND STATOR (FIELD) COILS.
- CO-91-93 DETAIL OF GENERAL ELECTRIC 250-HP SYNCHRONOUS MOTOR FROM DRIVE END. MOTOR BADGE PLATE READS 263 AMP, 400 VOLT, FRAME 6274-D #4940649, 250 HORSEPOWER, TYPE TSR, 3 PHASE, 60 CYCLE, SPEED 300 RPM.
- CO-91-94 OFFICE, CALLED THE "DOGHOUSE," BETWEEN GOLD JIGS AND FLOTATION AREA.
- CO-91-95 FLOTATION ROOM, LOOKING SOUTHWEST, WITH LEAD ROUGHER CELLS AT RIGHT AND LEAD CLEANER CELLS AT LEFT. NOTE SUNNYSIDE GOLD CORP. "SG" LOGO ON ROUGHER CELL LAUNDER.
- CO-91-96 CLARKSON MODEL E REAGENT FEEDER USED TO METER REAGENTS INTO FLOTATION CELL.
- CO-91-97 LEAD CLEANER CELLS, LOOKING SOUTH SOUTHWEST. NOTE SMALL HANDWHEELS FOR GATE VALVES USED TO ADJUST FLOW BETWEEN INDIVIDUAL CELLS.

SHENANDOAH-DIVES MILL
HAER CO-91
INDEX TO PHOTOGRAPHS
Page 11

- CO-91-98 LEAD SCAVENGER CELLS, LOOKING NORTHEAST. NOTE V-SHAPED LAUNDER TO COLLECT CONCENTRATE FROTH THAT SPILLED OVER WIER ALONG EDGE OF CELLS. EACH ELECTRIC MOTOR TURNED AGITATORS IN TWO CELLS VIA BELT DRIVES.
- CO-91-99 ZINC ROUGHER CELLS ON LEFT, ZINC CLEANER CELLS ON RIGHT, LOOKING NORTH. NOTE ONE STYLE OF DENVER AGITATOR IN LOWER RIGHT CELL.
- CO-91-100 DETAIL OF FLASH FLOTATION CELL INTERIOR. THIS CELL PERFORMED FIRST STAGE OF COPPER-LEAD SEPARATION.
- CO-91-101 DETAIL OF LEAD CLEANER CELL INTERIOR. NOTE SECOND STYLE OF DENVER AGITATOR.
- CO-91-102 DETAIL OF LEAD ROUGHER CELL INTERIOR. NOTE SEVERAL CELLS COMBINED INTO ONE LARGER CELL FOR THIS STAGE, DIPPER FOR SAMPLING SLIME, AND TWO DIFFERENT STYLES OF GALIGHER "AGITAIR" FIXED BAFFLES AROUND AGITATOR. GALIGHER AGITATORS HAVE PADDLE BLADES ON BOTTOM OF DISKS.
- CO-91-103 DETAIL OF ZINC CLEANER CELL INTERIOR (EXPOSED AT F/45 FOR DEPTH OF FIELD PURPOSES). NOTE GALIGHER STYLE BAFFLES AND TENDENCY OF ZINC TO BUILD UP ON CELL COMPONENTS.
- CO-91-104 PUMPS, CONDITIONING TANKS, AND ASSOCIATED PIPING LOCATED BELOW LEAD AND ZINC FLOTATION CELLS.
- CO-91-105 VIEW, LOOKING WEST, OF ONE OF TWO 35-FOOT DIAMETER DORR THICKENERS. THIS ONE USED FOR DEWATERING ZINC CONCENTRATE.
- CO-91-106 VIEW, LOOKING WEST, OF SECOND OF TWO 35-FOOT DIAMETER DORR THICKENERS. THIS ONE USED FOR DEWATERING LEAD CONCENTRATE.

SHENANDOAH-DIVES MILL

HAER CO-91
INDEX TO PHOTOGRAPHS
Page 12

- CO-91-107 VIEW OF DENVER AND EIMCO DISC FILTERS. DENVER FILTER AT LEFT USED FOR ZINC, AND EIMCO FILTER AT RIGHT USED FOR LEAD.
- CO-91-108 DETAIL OF DENVER DISC FILTER IN CO-91-107, SUCTION END. NOTE BEARING HOUSING WITH CAST LOGO, SUCTION PIPE GOING OFF TO THE RIGHT, AND FILTER DISC IN BACKGROUND. VACUUM INSIDE DISCS FURTHER DEWATERED CONCENTRATE. AS DISC SLOWLY ROTATED A BAR SCRAPED DRIED CONCENTRATE FROM OUTSIDE OF FILTER CLOTH.
- CO-91-109 DENVER DISC FILTER IN CO-91-107, SHOWING FIVE DOUBLE-SIDED DISCS AND DRIVE MOTOR. NOTE FOUR VERTICAL SLURRY FEED PIPES FROM OVERHEAD MANIFOLD AND SUCTION PIPE IN FOREGROUND.
- CO-91-110 DETAIL OF EIMCO DISC FILTER IN CO-91-107, SUCTION END. NOTE BEARING HOUSING AND SUCTION PIPE GOING OFF TO THE LEFT.
- CO-91-111 DETAIL OF FILTER DISCS ON DENVER FILTER IN CO-91-107. AS DISCS SLOWLY ROTATE, VACUUM INSIDE DISCS ATTRACT SLURRY IN THE SUMP AND DEWATERS CONCENTRATE AS DISCS MOVE THROUGH AIR. FURTHER ROTATION PASSES A BAR TO SCRAPE OFF DRIED METAL CONCENTRATE, ASSISTED BY BLASTS OF COMPRESSED AIR. METAL CONCENTRATE READY FOR SHIPMENT TO SMELTER FALLS INTO BIN BELOW. EIMCO FILTERS OPERATE SIMILARLY.
- CO-91-112 DETAIL OF ONE FILTER DISC LEAF, WITH CANVAS FILTER CLOTH REMOVED. NOTE SUCTION CHANNELS. OTHER SIDE IS IDENTICAL.
- CO-91-113 ENTRANCE TO GOLD AREA SECURITY ROOM IN BASEMENT, LOCATED IN BOTTOM OF ORIGINAL WET-BUCKET ELEVATOR SHAFT, ADJACENT TO DIESTER TABLE ROOM. NOTE BOARD WITH INDIVIDUAL TAGS FOR GOLD AREA EMPLOYEES.

- CO-91-114 VIEW, LOOKING NORTHEAST, OF CHEMISTRY LAB, LOCATED ON MEZZANINE ABOVE AND EAST OF FLOTATION CELLS. MAIN USE WAS SAMPLE ANALYSIS TO DETERMINE OPTIMUM REAGENT MIXES AND QUANTITIES.
- CO-91-115 VIEW, LOOKING SOUTH SOUTHWEST, OF SAMPLE PREPARATION AREA, LOCATED ON SOUTH CORNER OF PUMP DECK.
- CO-91-116 BUCKING PRESSES FOR REMOVING WATER FROM PROCESS SAMPLES.
- CO-91-117 VIEW, LOOKING NORTHWEST, OF DIESTER MODEL 6 CONCENTRATING (SHAKING) TABLE, USED FOR PRIMARY, MECHANICAL SEPARATION OF GOLD FROM ORE.
- CO-91-118 VIEW, LOOKING SOUTHWEST OF GOLD AMALGAMATION ROOM, SHOWING AMALGAMATION BARREL AT CENTER FOREGROUND, BULLION FURNACE IN LARGE HOOD BEHIND IT, AND GOLD RETORT IN BACKGROUND HOOD. NOTE OVERHEAD MONORAIL FOR MATERIALS HANDLING.
- CO-91-119 VIEW, LOOKING NORTHEAST, OF BULLION FURNACE AND HOOD AT RIGHT, AMALGAM PRESS ON STAND AT LEFT FOREGROUND, AND AMALGAMATION BARREL BEHIND IT.
- CO-91-120 VIEW, LOOKING SOUTHEAST, OF TELLURIDE IRON WORKS RETORT USED FOR FLASHING MERCURY OFF OF GOLD TO CREATE SOFT INGOTS CALLED "SPONGES." AT RIGHT ARE SAFES FOR STORING 22-POUND SPONGES WORTH OVER \$60,000 EACH, CA. 1985.
- CO-91-121 FRONT ELEVATION OF TELLURIDE IRON WORKS 2.5 BY 4-FOOT RETORT, USED TO FLASH MERCURY FROM GOLD. MERCURY VAPOR THEN CONDENSED ON INSIDE OF HOOD AND WAS COLLECTED FOR REUSE.

SHENANDOAH-DIVES MILL

HAER CO-91

INDEX TO PHOTOGRAPHS

Page 14

- | | |
|-----------|--|
| CO-91-122 | VIEW, LOOKING SOUTH, OF LATHE AND PORTION OF MAINTENANCE SHOP. |
| CO-91-123 | VIEW, LOOKING WEST TOWARD GRINDING AREA, OF MAINTENANCE SHOP. NOTE TRACK IN FLOOR FOR CARTS WITH HEAVY ITEMS, OVERHEAD JIB CRANE AT UPPER RIGHT, PARTIALLY OBSCURED "SG" LOGO ON CABINET, AND SIGNS ABOVE DOORWAY TO MILL. |

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

ADDENDUM TO:
SHENANDOAH-DIVES MILL
(Mayflower Mill)
135 County Road 2
Silverton
San Juan County
Colorado

HAER CO-91

Photographs HAER CO-91-1 through HAER CO-91-123 were previously transmitted to Library of Congress.

INDEX TO COLOR TRANSPARENCIES

Jet Lowe, photographer, 2005

| | |
|----------------|---|
| CO-91-124 (CT) | Tram Suspension Cable Oiling Car |
| CO-91-125 (CT) | View of town of Silverton, looking north |
| CO-91-126 (CT) | Shenandoah-Dives Mill Building, looking west |
| CO-91-127 (CT) | General view looking east-northeast from Tailings Pond to Shenandoah-Dives Mill |
| CO-91-128 (CT) | Shenandoah-Dives Mine Portal site, looking west |